



PROVIDE FIXED WARNING LABEL WITHIN POLE BASE

WARNING MULTIPLE SUPPLIES
ISOLATE ALL SUPPLIES AT ORIGIN OF SUPPLY/ DISTRIBUTION BOARD PRIOR TO COMMENCING ANY WORKS

TYPICAL WIRING SCHEMATIC
NOT TO SCALE